



Step-01


Holder with pipe and 3 S Hook






Step-02

Hold Glass drop by hand and Insert S hook in top 03 hole one by one in the glass shown as picture step -02




For straight alignment of Holder use screw driver for tightened steel cord and loose febric cord.




Assemble Picture of Drop

Step-03









Step-01


Holder with pipe and 3 S Hook






Step-02

Hold Glass drop by hand and Insert S hook in top 03 hole one by one in the glass shown as picture step -02




For straight alignment of Holder use screw driver for tightened steel cord and loose febric cord.




Assemble Picture of Drop

Step-03








Step-01


Holder with pipe and 3 S Hook






Step-02

Hold Glass drop by hand and Insert S hook in top 03 hole one by one in the glass shown as picture step -02




for tightened steel cord and loose febric cord.



Step-03

Assemble Picture of Drop





Mounting Assembly Instructions

