## Table Schickeria MDF Top & Steel Base

Tips:A clean rug or canvas drop cloth or carton should cover your work area before assembly, to avoid table top being scrached or nicked. The extra screws are spare parts. to avoid table top being scrached or nicked. The extra screws are spare parts.



to avoid table top solling coldened or more all ordered are opened parts.						
Square Plate x 1	Table Top x 1			1	2	Λ
				A D B D D D D D D D D D D D D D D D D D	A B D D D D D D D D D D D D D D D D D D	
Table Leg x 1						
	Α		6			
	В		10	3	4	
Table Base x 1	С		4	D C B		
	D		1			