











C-1051 ASSEMBLY INSTRUCTION

		 <p>① x1</p>	 <p>② x2</p>	 <p>③ x2</p>	 <p>M6×25MM ④ x12</p>	 <p>Ø16×Ø6 ⑤ x12</p>
---	---	---	---	---	--	---

 <p>Ø10×Ø6 ⑥ x12</p>	 <p>4# ⑦ x1</p>	 <p>Ø25×5 ⑧ x4</p>
---	--	---

